

<p style="text-align: center;">OTTAWA COUNTY ROAD COMMISSION</p> <p style="text-align: center;">OPERATIONAL POLICY TRAFFIC & SAFETY</p>	<p style="text-align: center;">NUMBER: 5</p> <p style="text-align: center;">EFFECTIVE DATE: 08/19/14</p> <p style="text-align: center;">REVISION NUMBER:</p>
<p style="text-align: center;">SUBJECT: GUIDELINES FOR SIGN UPGRADES AT AN INTERSECTION DUE TO NON-COMPLIANCE OF STOP CONDITION</p>	

This policy is to provide guidelines for sign upgrades at an intersection due to non-compliance of STOP condition.

1. Upgrade 30” Stop sign with 36” Stop sign (OCRC currently upgrading 30” Stop signs to 36” Stop signs on paved roads (excluding subdivision streets) as part of regular maintenance activities).
2. Install right side 36” Stop Ahead sign.
3. Install reflective panels on Stop sign posts.
4. Install reflective panels on Stop Ahead sign posts.
5. Install left side 36” Stop sign with reflective panels.
6. Install left side 36” Stop Ahead sign with reflective panels.
7. Install Flashing Beacon(s).

The above steps are intended as a guide. Engineering judgment should be used when determining what steps (if any) should be followed based on a review of conditions at the intersection.

Adopted by the Board of County Road Commissioners: August 19, 2014

This policy supersedes and rescinds the previous Guidelines for Sign Upgrades at an Intersection Due to Non-Compliance of Stop Condition Policy of September 25, 2008.